

Aviation Human Factors: Lessons from the Ashes



Robert Sumwalt
May 8, 2019



Human factors is a multidisciplinary science that examines the relationship between humans and the systems with which they interact, including...

Ergonomics
Engineering
Psychosocial interactions
Decision-making
TEM
Fatigue
Psychology
Physiology
Human-centered design
Information processing
Biomechanics
National cultural influences
Medicine
Study of organizational issues
Anthropometrics
CRM
Resilience engineering
Automation management
Communications

Aviation Human Performance Investigators



Evan Byrne, Ph.D.



Katherine Wilson, Ph.D.



Bill Bramble, Ph.D.



Sathya Silva, Ph.D.

NTSB Medical Officers



Mary Pat McKay, MD, MPH
Chief Medical Officer




Nicholas Webster, MD
Medical Officer



Michelle Watters, MD, PhD
Medical Officer

NTSB Investigations Examine the Entire System





Teterboro, NJ
May 15, 2017


DVR 1-Q12



- The pilot-in-command's (PIC) attempt to salvage an unstabilized visual approach, which resulted in an aerodynamic stall at low altitude.
- Contributing to the accident was the PIC's decision to allow an unapproved second-in-command to act as pilot flying, the PIC's inadequate and incomplete preflight planning, and the flight crew's lack of an approach briefing.

Also contributing to the accident were Trans-Pacific Jets' lack of safety programs that would have enabled the company to identify and correct patterns of poor performance and procedural noncompliance and the Federal Aviation Administration's ineffective Safety Assurance System procedures, which failed to identify these company oversight deficiencies.

Potential Sources of Information





Thomson, GA
February 20, 2013



Google earth

Google earth

Imagery Date: 1/29/2015 33°31'41.29" N 82°30'08.01" W elev 498 ft eye alt 4135

Pilot activities

Night before trip		
	Went to bed	2100
	5 hours	
Day of trip		
	Woke up	0200
	Departed home	0230
	Arrived airport	0330
	Departed for Nashville	0406
	Arrived Nashville	0459*
	Lunch 14 hours	1500 – 1630*
	Passengers arrived	1918*
	Takeoff Nashville	1927*
	Crash at Thomson, GA	2005

* Times converted to EST

Time	Cell phone activity
0808	Phone call - outgoing
0813	Phone call - outgoing
0902	Phone call - outgoing
1002	Text message - outgoing
1005	Text message - outgoing
1016	Text message - outgoing
1121	Text message - outgoing
1138	Phone call - outgoing
1234	Phone call - outgoing
1251	Phone call - outgoing
1300	Phone call - outgoing
1315	Phone call - outgoing
1317	Phone call - outgoing
1324	Phone call - outgoing
1330	Phone call - outgoing
1332	Phone call - outgoing
1404	Text message - outgoing
1432	Phone call - outgoing
1501	Phone call - outgoing
1503	Phone call - outgoing
1642	Phone call - outgoing

1 Incoming call

2 Incoming calls

2 Incoming calls

2 Incoming calls

2 Incoming calls

1 Incoming call

1 Incoming call



National Transportation Safety Board

Loss of Control Eurocopter AS350

Las Vegas, Nevada
December 7, 2011



Fuselage
and engine



Recommendation

Maintenance personnel should receive initial and recurrent training on maintenance human factors, including:

- a review of the causes of human error
- fatigue

Lockhart, TX
July 30, 2016



Pilot's Medications

- Prescribed 13 medications

Many likely not impairing

- Toxicology: 5 likely impairing medications

Three prescription

Cyclobenzaprine, diazepam, oxycodone

Two over-the-counter

Dextromethorphan, diphenhydramine



Asiana flight 214



- July 6, 2013
- San Francisco, California
- 3 Fatalities

Probable Cause

- The flight crew's mismanagement of the airplane's descent during the visual approach
- The pilot flying's unintended deactivation of automatic airspeed control
- The flight crew's **inadequate monitoring** of airspeed
- The flight crew's delayed execution of a go-around after they became aware that the airplane was below acceptable glidepath and airspeed tolerances.

Contributing to the accident:

- (1) the complexities of the **autothrottle** and **autopilot flight director systems** that were inadequately described in Boeing's documentation and Asiana's pilot training, which increased the likelihood of mode error
- (2) the flight crew's nonstandard **communication** and coordination regarding the use of the autothrottle and autopilot flight director systems
- (3) the pilot flying's inadequate **training** on the planning and executing of visual approaches
- (4) the pilot monitoring/instructor pilot's inadequate supervision of the pilot flying
- (5) flight crew **fatigue** which likely degraded their performance.



Aircraft Design Human Factors

System Safety Order of Precedence*

1. Eliminate the hazard through **Design/Engineering Features**
 - Hazard is corrected and eliminated
2. Incorporate **Guards/Safety Devices**
 - Guards put up to decrease exposure
3. Provide **Warning Devices**
 - Warn personnel if you can't eliminate or control the hazard
4. Develop **Procedures and Training**


*Also know as “Hierarchy of Controls.”

Source: MIL-STD-882E

ROBERT'S HF PREMISE # 1

If you design out the problem, you design out the problem.

<duh>



ROBERT'S HF PREMISE # 2

If you design something with enough complexity,
don't be surprised if someone can't use it when they
really need it.

American 383, October 28, 2016



Rejected takeoff



Evacuation



ROBERT'S HF PREMISE # 3

If you don't account for human error, you, yourself, have made a very basic human error.


In-Flight Breakup During Test Flight


October 31, 2014

SpaceShipTwo











SpaceShipTwo Feather System




Feather retracted



Feather extended

PROBLEM: During the transonic region, the upward aerodynamic forces acting on the feather exceeded the ability of the feather actuators to keep the feather retracted.

SOLUTION:
Provide
mechanical
locks to keep
feather
retracted during
this region.



Feather Lock Handle



Feather Locked


Lock
↑
↓
Unlock



Feather Unlocked

PROBLEM: If feather could not be unlocked, it would pose a very high risk (probably catastrophic) reentry.

SOLUTION: Unlock feather at 1.4 Mach.



If not unlocked at 1.5 Mach, cockpit alert.
If not unlocked at 1.8 Mach, mission abort.

Specified Flight Crew Procedures




Specified Flight Crew Procedures



Specified Flight Crew Procedures

<u>PILOT</u>		<u>COPLOT</u>
Action: Vehicle control Verbal command: "Fire"	WK2 release	Action: Ignite rocket motor
	0.8 Mach	Verbal call: "0.8 Mach"
	Transonic bobble	
Action: Trim stabilizer		Verbal call: "Stabs (degrees)"

Specified Flight Crew Procedures



What actually occurred

- Copilot made 0.8 Mach callout
- At 0.82 Mach, called out “unlocking” and moved feather handle to unlocked position
- Video and telemetry stopped



DCA15MA019
SCALED COMPOSITES
SPACESHIPTWO
N339SS
POWERED FLIGHT #4



The investigation found

- High emphasis on making sure feather was unlocked at 1.4 Mach.
 - Cockpit visual and aural alerting
 - Training and procedures
 - Mission abort if not unlocked by 1.8 Mach
- Not great concern placed on low speed unlocking.
 - Relied on pilots to do it right

- A single-point mechanical failure with catastrophic consequences would be unacceptable.
- However, Scaled Composites failed to consider that a single human error could be catastrophic.

NTSB Finding

“By not considering human error as a potential cause of uncommanded feather extension on the SpaceShipTwo vehicle, Scaled Composites missed opportunities to identify the design and/or operational requirements that could have mitigated the consequences of human error during a high workload phase of flight.”

Probable Cause of the Accident

- “Scaled Composites’ failure to consider and protect against the possibility that a single human error could result in a catastrophic hazard to the SpaceShipTwo vehicle.
- This failure set the stage for the copilot’s premature unlocking of the feather system as a result of time pressure and vibration and loads that he had not recently experienced, which led to uncommanded feather extension and the subsequent aerodynamic overload and in-flight breakup of the vehicle.”

NTSB Recommendation



Develop and issue human factors guidance for use during the design and operation of crewed vehicles.



National Transportation Safety Board